PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 45, REV. 1 FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

NOMENCLATURE AND PART NUMBER	APPROVED REPLACEMENT FOR	FAA DESIGN DATA AND APPROVAL MEANS	APPROVED FOR INSTALLATION ON
SA5001 Ring	Teledyne Continental Part No. 630752	FAA approved Superior Air Parts, Inc. Dwg. No. SA5001 Rev. n/c dtd. 04/07/75 or later FAA approved revision.	Continental Eng. 10-520-M TSIO-520-M, N, P,
SA5002 Ring	Teledyne Continental Part No. 630753	FAA approved Superior Air Parts, Inc. Dwg. No. SA5002 Rev. n/c dtd. 06/29/76 or later FAA approved revision.	Continental Eng. 10-520-M TSI0-520-M, N, P,
SA629690 Assembly, ton pin	Teledyne Continental Part No. 629690	FAA approved Superior Air Parts, Inc. Dwg. No. SA629690 Rev. n/c dtd. 10/29/81 or later FAA approved revision.	Continental Eng. 10-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB
			LTSIO-360-E, EB,

PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 45, REV. 1 FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

NOMENCLATURE AND PART NUMBER	APPROVED REPLACEMENT FOR	FAA DESIGN DATA AND APPROVAL MEANS	APPROVED FOR INSTALLATION ON
SA629690 Assembly, piston pin (cont'd)	Teledyne Continental Part No. 629690	FAA approved Superior Air Parts, Inc. Dwg. No. SA629690 Rev. n/c dtd. 10/29/81 or later FAA approved revision.	Continental Eng. TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, GB, H, HB, JB, KB, LB, MB

END OF LISTING

Aller K. Griggs Manager, DFW MIDO-42

9-28-93

Date

Date amended: 09/07/93

Date of original approval: 02/10/82

Revision 1 added new engine models to the eligibility listing and removed parts that were superseded or are no longer used.

This supplement is an attachment to FAA-PMA letter dated 06/11/79.